


RATBY CONSERVATION AREA MANAGEMENT PLAN - ADOPTED 4 FEBRUARY 2014

The rustic character of Church Lane and Chapel Lane would be enhanced if heritage street lighting was installed



This section of churchyard wall is starting to bulge and is to be re-built

This area would be improved if the back edge of the footpath was defined with granite setts and the entrance re-surfaced with macadam or setts

This unsightly timber fence needs replacing with a stone wall

The timber fence running along Burroughs Road needs repairing

The large expanse of car parking dominates the road junction and would benefit if broken up with landscaping

The views up this access would be improved if the timber fence was replaced with a traditional wall

This garage site is visually poor, particularly the rear garage court and brick wall. The redevelopment of the site will help improve the lower end of Berry's Lane

The visual prominence of this car park would be reduced with the construction of a traditional brick wall along part of its frontage

The timber fence fronting this property is visually poor. Consideration should be given to replacing it with a traditional wall

The appearance of this terrace would be enhanced if the roofing materials were all changed to slate

The original granite setts hidden beneath the macadam should be taken up and relaid

This large area of macadam needs reducing in size by providing a strip of granite setts across the entrance

It is suggested that the more interesting heritage buildings could be identified by having information plaques erected

The car parking information sign needs re-erecting